

Work Order ID 59013

Friday, May 21, 2010 10:56:54 AM



Page 1

Item ID: D3836-042

Accept



Setup Start



Revision ID:

Item Name: Rib Assembly (Basket Lid, RH)

Stop



Start Date: 5/21/2010 Start Qty: 2.00



Cust Item ID:

Required Date: 5/31/2010 Req'd Qty: 2.00



Customer:

Reference:

Approvals: Process Plan:



Date: 10-5-21 Tooling:

Date:

Run Start



QC:

Date: SPC (Y/N):

Date:

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run HoursDraw
NumberDraw
Rev.Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

Draw Nbr	Revision Nbr
D3836	Rev A

100



Large Fab

0.00

Large Fab

Memo

0.00

Large Fab

1- cut D3836-2 and D3836-3 rib as per dwg D3836

2- remove identification markings

3- deburr

4- weld D3836-2 to D3836-3 and drill hole (3/16") using DT9447 jig and open to finish size as per dwg D3836

5- weld D2327-3 spacer bushing as per dwg D3836

A/R ER316 S.S. Rod Batch: 4113328

6- grind weld flush where indicated on dwg

② 10/05/13

SAD 10-05-27

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____
 Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 59013

Friday, May 21, 2010 10:56:54 AM



Page 3

Item ID: D3836-042

Accept



Setup

Start



Revision ID:

Item Name: Rib Assembly (Basket Lid, RH)

Stop



Start Date: 5/21/2010 Start Qty: 2.00



Cust Item ID:

Required Date: 5/31/2010 Req'd Qty: 2.00



Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run

Start



QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/
Work Center ID

160

Operation
Description

QC21- Final Inspection - Work Order Release

Set Up/
Run Hours

0.00

Draw
NumberDraw
Rev.Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

QC

Quality Control

Memo

0.00

10/06/10 JH

C2101611

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____
 Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Friday, May 21, 2010 10:56:59 AM

Page 1

Work Order ID: 59013



Parent Item: D3836-042



Parent Item Name: Rib Assembly (Basket Lid, RH)

Start Date: 5/21/2010

Required Date: 5/31/2010

Comments: IPP Rev:A 08-12-01 new issue DD verified by:eC

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

D2327-3



Manufactured

No

100

Each

1.0000

1

2



B58406 @ M 10/05/31

Spacer Bushing

Location	Loc Qty	Loc Code
----------	---------	----------

.WA

1

57790

1

M304TS0.750W.065



Purchased

No

100

f

1,200.557

1.7808

3.749053



SAD 10-05-28

304 SQ Tube .75x.75x.065W

Location	Loc Qty	Loc Code
----------	---------	----------

MAT

200.5571

112398

0

114482

200.5571

3.7490

WA

1000

114520

1000

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

8 7 6 5 4 3 2 1

ITEM	QTY -041	QTY -042	P/N	DESCRIPTION
1	X		D3836-041	RIB ASSY (BASKET LID, LH)
2		X	D3836-042	RIB ASSY (BASKET LID, RH)
3	1	1	D2327-3	SPACER BUSHING
4	1		D3836-1	RIB
5		1	D3836-2	RIB
6	1	1	D3836-3	RIB

D3836-042 RIB ASSY (BASKET LID, RH)

D3836-041 RIB ASSY (BASKET LID, LH)

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 59013
PLA 5-21

RELEASED
06/11/RMWD

A	NEW ISSUE	MB	08.09.24
REV.		BY	DATE
DESIGN		DART AEROSPACE LTD	
DRAWN		HAWKESBURY, ONTARIO, CANADA	
CHECKED	<i>PLA</i>	DRAWING NO.	REV. A
MFG. APPR.	<i>PLA</i>	D3836	SHEET 1 OF 3
APPROVED	<i>PLA</i>	TITLE	SCALE
DE APPR.	<i>PLA</i>	RIB ASSY (BASKET LID)	
DATE	08.09.24	NTS	

COPYRIGHT © 2008 BY DART AEROSPACE LTD.
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL. AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS
NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT
WRITTEN PERMISSION FROM DART AEROSPACE LTD.

8 7 6 5 4 3 2 1

- NOTES:**
- 1) MATERIAL: N/A
 - 2) FINISH: NONE
 - 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
 - 4) UNITS: INCHES UNLESS OTHERWISE NOTED
 - 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
 - 6) IDENTIFICATION: N/A
 - 7) WEIGHT: 0.99 lbs EACH
 - 8) WELD PER DART QSI 004


W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



W/0 59013

DESIGN		DART AEROSPACE LTD	
DRAWN		HAWKESBURY, ONTARIO, CANADA	
CHECKED		DRAWING NO.	
MFG. APPR.		D3836	
APPROVED		REV. A	
DE APPR.		SHEET 2 OF 3	
DATE	08.09.24	TITLE	SCALE
		RIB ASSY (BASKET LID)	
		NTS	

COPYRIGHT © 2008 BY DART AEROSPACE LTD
THIS DOCUMENT IS PROPRIETARY AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS
NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT
WRITTEN PERMISSION FROM DART AEROSPACE LTD






W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____
 Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

8 7 6 5 4 3 2 1

0.75 X 45°
CHAMFER $\phi 0.375^{+0.020}_{-0.000}$ THRUD3836-1 RIB0.75 X 45°
CHAMFERD3836-3 RIB0.75 X 45°
CHAMFER $\phi 0.375^{+0.020}_{-0.000}$ THRUD3836-2 RIBTYPICAL SECTION
VIEWRELEASED
(03/11/08)

A

NOTES:

- 1) MATERIAL: AISI 304/316 STAINLESS STEEL SQUARE TUBE, 0.75 X 0.75 X 0.065 WALL
REF. DART SPEC. M304TS0.750W0.065
 - 2) FINISH: NONE
 - 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
 - 4) UNITS: INCHES UNLESS OTHERWISE NOTED
 - 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
 - 6) IDENTIFICATION: N/A
 - 7) WEIGHT: D3836-2 = 0.78 lbs EACH; D3836-3 = 0.19 lbs
- W059019*

8 7 6 5 4 3 2 1

DESIGN	<i>1</i>	DART AEROSPACE LTD	
DRAWN	<i>5</i>	HAWKESBURY, ONTARIO, CANADA	
CHECKED	<i>ASS</i>	DRAWING NO.	REV. A
MFG. APPR.	<i>MP</i>	D3836	SHEET 3 OF 3
APPROVED	<i>MP</i>	TITLE	SCALE
DE APPR.	<i>MP</i>	RIB ASSY (BASKET LID)	NTS
DATE	08.09.24	COPYRIGHT © 2008 BY DART AEROSPACE LTD THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION. IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD	

A

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____
 Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries